while also improving cleaning, safety & bottle appearance

Solution Story

CHALLENGE

A winery and bottling facility bottling 13,000-18,000 bottles/hour at 60-86° F was using a wet lubrication. The winery was looking for ways to reduce water usage and improve the bottling hall hygiene environment.

SOLUTION

The facility partnered with Ecolab to switch from a wet lubricant to DryExx GF, a highly effective, semi-dry conveyor lubricant which eliminates the majority of water needed while maintaining hygiene and efficiency.

RESULTS



Significantly REDUCED conveyor lubrication while meeting required hygiene standards





The bottling hall floor is drier, reducing potential for worker slips and falls





IMPROVED bottle appearance





